

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| M | A | P | P | S | I | | 00-000000-000 | | 1111 | |

CON'T
 | REPORT SOURCE L | | 050-0293 | | 021483 | | 031683 |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

| An inspection of the former I&C Lab, during its conversion to office space, revealed
 | apparent deviations from T.S. section 3.12F fire barrier requirements. Due to the
 | continuous presence of control room personnel trained in fire fighting, in the
 | adjacent main control room, the T.S. action requirement of a fire watch on one side
 | of the barrier has been in place since plant startup.
 | _____
 | _____

| SYSTEM CODE A B | CAUSE CODE B | CAUSE SUBCODE Z | COMPONENT CODE Z Z Z Z Z Z | COMP. SUBCODE Z | VALVE SUBCODE Z

| LER/RO REPORT NUMBER 83 | EVENT YEAR 83 | SEQUENTIAL REPORT NO. 008 | OCCURRENCE CODE 03 | REPORT TYPE L | REVISION NO. 0

| ACTION TAKEN X | FUTURE ACTION X | EFFECT ON PLANT Z | SHUTDOWN METHOD Z | HOURS 0000 | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. N | PRIME COMP. SUPPLIER Z | COMPONENT MANUFACTURER Z999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

| These conditions have existed since initial construction and were not discovered
 | during the plant retrofit for compliance with Amendment 35 to PNPS T.S. relating to
 | fire protection. A plan to correct these deficiencies is being formulated.
 | _____
 | _____

| FACILITY STATUS G | % POWER 000 | OTHER STATUS NA | METHOD OF DISCOVERY C | DISCOVERY DESCRIPTION Fire Protection

| ACTIVITY CONTENT Z | AMOUNT OF ACTIVITY NA | LOCATION OF RELEASE NA

| PERSONNEL EXPOSURES NUMBER 000 | TYPE Z | DESCRIPTION NA

| PERSONNEL INJURIES NUMBER 000 | DESCRIPTION NA

| LOSS OF OR DAMAGE TO FACILITY TYPE Z | DESCRIPTION NA

| PUBLICITY ISSUED N | DESCRIPTION NA

8303250121 830316
 PDR ADOCK 05000293
 S PDR

NAME OF PREPARER G.G. Whitney PHONE 617-746-7900

GPO 517-926