

APPENDIX A

ITT Grinnell Corporation
Pipe Hanger Division
Engineering Department
Docket No. 99900285/82-02

NOTICE OF VIOLATION

As a result of the inspection conducted on November 15-18, 1982, and in accordance with Section 206 of the Energy Reorganization Act of 1974 and its implementing regulation 10 CFR Part 21, the following violation was identified and has been categorized in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987 (March 9, 1982):

Section 21.21 of 10 CFR Part 21 states, in part, "(a) Each individual, corporation, partnership or other entity subject to the regulations in this part shall adopt appropriate procedures to (1) provide for (i) evaluating deviations or (ii) informing the licensee or purchaser of the deviation in order that the licensee or purchaser may cause the deviation to be evaluated unless the deviation has been corrected"

Contrary to the above, ITT Grinnell (ITT) was notified by a customer on October 9, 1978, that dimensional conditions existed in certain mechanical shock and sway suppressors which would preclude the ability for the units to achieve a 10^0 included angle cone of action to the pipe clamp axis.

ITT, after reviewing the identified conditions, revised their drawings and informed the customer as to the necessary actions required to bring the units into compliance. However, as of the date of this inspection, ITT had neither formally evaluated the identified conditions nor notified any other purchaser of similarly affected units in order for the conditions to be evaluated and/or corrected.

This is a Severity Level IV Violation (Supplement VII).