

MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

October 13, 1982

JAMES P. McGAUGHY, JR.

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station

Unit 1 Docket No. 50-416 License No. NPF-13

File 0260/L-835.0 Secondary Containment

Integrity - Two 2" Penetrations Not Sealed Reference: LER 82-077/01 T-0 AECM-82/481

On September 30, 1982, it was discovered that two 2" penetrations were not sealed from the Auxiliary Building to the Control Building. T.S.3.6.6.1 and 3.0.4 were applicable when operational condition 3 was entered during nonnuclear heatup. Attached is LER 82-077/01 T-0.

John & Blubaule. .

JPM: sap Attachment

cc: Mr. N. L. Stampley (w/a)

Mr. R. B. McGehee (w/o) Mr. T. B. Conner (w/o)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555

JE-22

8210190417 821013 PDR ADDCK 0500041