




**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631



October 8, 1982  
RBG- 13,503  
File Nos. 69.5, 69.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Interim Report/DR-74

On August 30, 1982, Gulf States Utilities Company (GSU) notified the Nuclear Regulatory Commission's Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning the incorrect installation of 1/4 inch drilled-in-expansion-type anchor bolts used to seismically support emergency lighting battery units in the River Bend Station control room (DR-74). GSU has not completed its investigation at this time. An interim or final status report will be provided by January 28, 1983.

Sincerely,

*William J. Booker*  
for J. E. Booker  
Manager-Engineering & Licensing  
River Bend Nuclear Group

*JEB*  
JEB/RJR/kt

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

R. L. Brown (RRI)

*IE27*