O PSEG

Gertified By Mar

Public Service Electric and Gas Company P.O. Box E. Hancocks Bridge, New Jersey 08038

Salem Generating Station

October 12, 1982

Mr. R. C. Haynes
Regional Administrator
USNRC
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:

REPORTABLE OCCURRENCE 82-119/01P SALEM NO. 2 UNIT LER

This letter is to confirm our verbal report to the NRC Headquarters on Friday, October 8, 1982, advising of a potential reportable occurrence in accordance with IE Bulletin 80-24.

During routine power operation, a service water leak was discovered inside the Containment Building, on No. 21 Containment Fan Coil Unit. The leak rate was approximately 0.5 gallons per minute, and the leak has been isolated.

An investigation is in progress, and a detailed report will be submitted in the time period specified by IE Bulletin

Sincerely yours,

N. g. refisher

H. J. Midura
General Manager Salem Operations

RF:ks

CC: Distribution

TER9