## LICENSEE EVENT REPORT

	CONTROL BLOCK: [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	I L Z   I S   1 3 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5
0 1 7 8	SOURCE LO   5   0   0   0   2   9   5   7   0   9   0   5   8   2   8   1   0   0   5   8   2   9   9   9   9   9   9   9   9   9
0 2	On 9/05/82 at 0225 hours during daily plant rounds, 1C Containment
0 3	Spray Diesel Driven Pump was found completely void of engine jacket
0 4	water. The diesel was declared inoperable thus TS 3.6.1.B was
0 5	[violated (requires 3 operational pumps). There were no safety impli-
0 6	cations since redundunt systems were operable. This is the first
0 7	event of this type.
0 3	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	S CODE SUBCODE COMPONENT CODE SUBCODE
	LER/RO EVENT YEAR REPORT NO.  17) REPORT NUMBER 21 22 23 24 26 27 10 3 LL 30 30 30 30 30 30 30 30 30 30 30 30 30
1 0	The loss of coolant inventory was caused by a leak developed in the
1 1	
	jacket water heater due to corrosion. Temporary repair has been made
1 2	by replacing the heater with a pipe plug to maintain water tight
1 3	
1 3	by replacing the heater with a pipe plug to maintain water tight  [integrity. New heaters are on order for both units and they will be  [installed when received. No further action is necessary.
1 3	by replacing the heater with a pipe plug to maintain water tight  integrity. New heaters are on order for both units and they will be  installed when received. No further action is necessary.  installed when received. No further action is necessary.  STATUS  **POWER OTHER STATUS **  DISCOVERY DESCRIPTION (32)    E   (28)   1   0   0   (29)   NA     B   (31)   Plant Rounds
1 3 1 4 7 8 1 5 7 8	by replacing the heater with a pipe plug to maintain water tight  integrity. New heaters are on order for both units and they will be  installed when received. No further action is necessary.  PACILITY STATUS  A POWER OTHER STATUS  OTHER ST
1 3 7 8 1 5 7 3 A	by replacing the heater with a pipe plug to maintain water tight  integrity. New heaters are on order for both units and they will be  installed when received. No further action is necessary.    Installed when received. No further action is necessary.   Installed when receive
1 3 7 8 1 5 7 3 A	by replacing the heater with a pipe plug to maintain water tight  integrity. New heaters are on order for both units and they will be  installed when received. No further action is necessary.  installed when received. No further action is necessary
1 3 7 8 1 5 7 3 A	by replacing the heater with a pipe plug to maintain water tight  integrity. New heaters are on order for both units and they will be  installed when received. No further action is necessary.    10
1 3 1 4 7 8 1 5 7 8 1 7 7 8	by replacing the heater with a pipe plug to maintain water tight  integrity. New heaters are on order for both units and they will be  installed when received. No further action is necessary.    Constant   Con