

Appendix

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-373

As a result of the inspection conducted on February 1 - March 10, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

Technical Specification 6.2 requires, in part, that detailed written procedures including applicable checkoff lists be prepared, approved, and adhered to for the applicable procedures recommended in Appendix "A" of Regulatory Guide 1.33, Revision 2, February 1978. Appendix "A" of the referenced Regulatory Guide recommends procedures for equipment control (e.g., locking, tagging). LaSalle Administrative Procedure LAP 240-1 requires that valves 1PC007B and 1PC008B ("B" Suppression Pool Vacuum Breaker Test Connections) be locked shut.

Contrary to the above, on February 21, 1983, valves 1PC007B and 1PC008B were found shut but unlocked.

This is a Severity Level V violation (Supplement I).

The inspection showed that action had been taken to correct the identified item of noncompliance and to prevent recurrence. Consequently, no reply to this item of noncompliance is required and we have no further questions regarding this matter.

4-6-83
Dated

W.D. Shafer
W. D. Shafer, Chief
Projects Branch 2