




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

L. V. MAURIN
Vice President
Nuclear Operations

October 15, 1982

W3182-0075
Q-3-A35.07.31



Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382 \\
Significant Construction Deficiency Report No. 31
"Incorrect Friction Factor Used In Design of Pipe Support Hangers"
Third Interim Report

REFERENCES: (1) LP&L Letter W3K81-0275 Dated July 29, 1981
(2) LP&L Letter W3K82-0201 Dated April 2, 1982

Dear Mr. Collins:

At the present time, 295 of the 298 hangers have been reworked. The only hangers that have not been reworked are CDSH-60, CSRS-51, and HDSH-108. Due to late delivery of parts on the three (3) remaining hangers, completion of corrective action has been delayed. A final report will, therefore, be transmitted by July 13, 1983.

Very truly yours,


L. V. Maurin

LVM/MAL:keh

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE 27

82102503415