

SUPPLEMENT TO DVR

DVR NO.	STA	UNIT,	YEAR	NO.
D -	12	- 3	- 82	- 37

PART 1	TITLE OF EVENT	OCCURRED	
	Failure of RBM to Function for Ten Control Rods	<u>5/10/82</u>	<u>1845</u>
		DATE	TIME
	REASON FOR SUPPLEMENTAL REPORT		
	To correct the licensee code and docket number from a Unit 2 code and docket number to a Unit 3 code and docket number.		
PART 2			
	ACCEPTANCE BY STATION REVIEW	<u>J. Brunner</u>	<u>Michael D. Wright</u>
	DATE	<u>9/24/82</u>	<u>9-29-82</u>
	SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u>Douglas K. O'Neil</u>	<u>9/30/82</u>
		STATION SUPERINTENDENT	DATE