



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215/770-5151

October 14, 1982

Mr. R.C. Haynes  
Director, Region I  
U.S. Nuclear Regulatory Commission  
63i Park Avenue  
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 82-025/01P-0  
ER 100450 FILE 841-23  
PLA-1344

Docket No. 50-387  
License No. NPF-14

Dear Mr. Haynes:

This transmission confirms the telephone report of October 13, 1982, by D.G. Mitchell to Mr. Keimig of your staff, regarding the inability to comply with an action statement. The chlorine detectors were inoperable and the action statement requires one Control Room Emergency Outside Air Supply System be placed in the recirculation mode. However, both CREOASS trains were out of service while being worked on, as allowed by the action statements. Therefore, the chlorine detector action statement could not be met.

This condition is considered reportable in accordance with Technical Specification 6.9.1.8.b.

H.W. Keiser  
Superintendent of Plant-Susquehanna

DGM/cw

cc: Richard C. DeYoung - Director, Office of Inspection and Enforcement  
Norman H. Haller - Director, Office of Management and Program Control  
U.S.N.R.C. - Resident Inspector, Susquehanna SES

8210250357 5

1E29