

Certified By

*Maf***YANKEE ATOMIC ELECTRIC COMPANY**

Rowe, Massachusetts 01367

October 7, 1982

Mr. R. C. Haynes, Director  
 U. S. Nuclear Regulatory Agency  
 Office of Inspection and Enforcement  
 Region I  
 631 Park Avenue  
 King of Prussia, Pennsylvania 19406

Subject: 24 Hour Notification Of LER 50-29/82-32

Dear Mr. Haynes:

In accordance with Technical Specifications, Section 6.9.4.a(3) the following is reported as LER 50-29/82-32 01T.

As reported in our telephone conversation at 0910 hours on 10/7/82, a positive indication was observed during the shpping of second cycle fuel assembly B-578 as performed on the 10/6/82 4-12 shift. Analysis indicates that this assembly probably was the cause for the slight increase in reactor coolant activity during Core 15 operation. Since B-578 is second cycle fuel, it will be replaced as scheduled with a new assembly.

A more detailed report will follow within 14 days.

Very truly yours,

*Herbert A. Antio*

Herbert A. Antio  
 Plant Superintendent

HAA  
 /  
 mcg