## DUKE POWER COMPANY P.O. BOX 33189 CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION 21 AID . 13

TELEPHONE (704) 373-4531

April 15, 1983

Mr. James P. O'Reilly, Regional Administrator U. S. Nuclear Regulatory Commission Region II
101 Marietta Street, NW, Suite 2900
Allanta, Georgia 30303

Subject: Oconee Nuclear Station

RO-287/83-04 RO-269/83-05 RO-269/83-10

Dear Sir:

The above Licensee Event Reports were due to be submitted by today. RO-287/83-04 concerns the failure to close a valve on the pressurization line to the Emergency Personnel Air Lock following quarterly performance testing. RO-269/83-05 concerns the failure to meet design criteria on the tie-in of the Standby Shutdown Facility reactor coolant make-up pump to the existing plant. RO-269/83-10 concerns the failure to close the inner door of the Emergency Personnel Air Lock following quarterly performance testing. These events were briefly discussed with you and your Staff on March 23, 1983. These reports are currently in the process of review and final preparation and will be submitted as soon as possible, but in any event, no later than April 19, 1983.

Very truly yours,

Hal B Tocher

Hal B. Tucker

RLG/php

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339 Mr. J. C. Bryant NRC Resident Inspector Oconee Nuclear Station

Mr. E. L. Conner, Jr.
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY