## LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M A Y K R I 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 TOTAL SE TYPE 30 57 CAT 58 5
REPORT SOURCE L 6 0 5 0 0 0 0 2 9 0 0 3 2 5 8 3 8 0 4 2 2 8 3 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  During normal operations while performing fire protection system modific
[0]3 lations, the special hazards header was taken out of service for one hour
[0]4 [and five minutes. The systems supplied are required to be operable by T.]
o 6 system. A continuous fire watch with backup suppression equipment was pr
o 7 [ovided throughout the outage. There was no adverse effect on the health
ols or safety as a result of this occurrence.
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
CODE   TYPE   NO.   CODE   TYPE
The cause of this occurrence was the removal of the header from service
[1] to allow the installation of the control room post accident filter syste
1 m sprinkler protection. The installation of the sprinkler system will im
13 prove the fire protection system's effectiveness, therefore, no correcti
1 4 Lye actions were taken or will be necessary in the future.
FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  1 5 E 28 1 0 0 29 NA A 44 45 46 Design Change Installation 80
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  NA  PERSONNEL EXPOSURES  AMOUNT OF ACTIVITY (35)  NA  44  45  LOCATION OF RELEASE (36)  NA  80
1 7 NUMBER O 37 Z 38 DESCRIPTION (39)  NA  NA  80  8304280112 830423
NUMBER OF O O O O O O O O O O O O O O O O O O
LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION  NA  NA  80
PUBLICITY ISSUED DESCRIPTION 45  NA  NA  NA  NA  NA  NA  NA  NA  NA  N
NAME OF PREPARER E. L. May PHONE: (413) 625-6140