DUKE POWER COMPANY

P.O. BOX 33189 CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT

April 22, 1983

Mr. James P. O'Reilly, Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street NW, Suite 2900 Atlanta, Georgia 30303

Re: McGuire Nuclear Station Units 1 and 2 Docket Nos. 50-369 and 50-370

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Reports RO-369/83-15 and RO-370/83-03. These reports concern T.S. 3.3.1, "As a minimum, the reactor trip system instrumentation channels and interlocks of Table 3.3-1 shall be operable with response times as shown in Table 3.3-2". This incident was considered to be of no significance with respect to the health and safety of the public.

A detailed report on the reactor trip breaker failures which are the subject of these reportable occurrence reports has been previously submitted to Mr. H. R. Denton (NRC/ONRR) by my letter of April 18, 1983, and should be considered an attachment to these two reports. Note that these or similar reactor trip breaker failures were the subject of NRC/OIE Bulletins 83-01 and 83-04, NRC/OIE circular 81-12, and NRC/OIE information notice 83-18. Additional correspondence on this issue includes my letters to Mr. Denton dated February 28, and March 1, 1983; my letters to you dated March 2 and 22, 1983; and Ms. E. G. Adensam's (NRC/ONRR) letter to me dated April 1, 1983. Further, a meeting was held between Duke Power Company and the NRC on April 19, 1983, at which time these incidents were discussed in detail.

Very truly yours,

H.B. Tucker / Mel

PBN:jfw Attachments

CC: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders NRC Resident Inspector McGuire Nuclear Station Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, Georgia 30339

8304280215 830422 PDR ADOCK 05000369 S PDR

IE 22

TELEPHONE (204) 373-4531