James A. FitzPatrick
Nuclear Power Plant
P.O. Box 41
Lycoming, New York 13093
315 342-3840



Harry P. Salmon, Jr. Resident Manager

June 13, 1994 JAFP-94-0302

United States Nuclear Regulatory Commission Document Control Desk Mail Station P1-137 Washington, D.C. 20555

SUBJECT: DOCKET NO. 50-333

LICENSEE EVENT REPORT: LER-91-010-01:

Emergency Diesel Generators Potentially inoperable due to Fire Protection Deficiencies

Dear Sir:

This supplementary report is submitted in accordance with 10CFR50.73(a)(2)(ii) and (v). This is a final report which describes the root cause for the reported deficiencies and provides final analysis results for 19 ventilation fire dampers which were rendered potentially inoperable because of inadequate installation or maintenance. Analysis is also provided for emergency diesel operability concerns due to intentional long term closure of four carbon dioxide actuated fire dampers in the ventilation systems for the emergency diesel generator switchgear rooms.

Questions concerning this report may be addressed to Mr. Donald Simpson at (315) 349-6361.

Very truly yours,

HARRY P. SALMON, OR.

HPS:DES:tlc

Enclosure

cc: USNRC, Region I USNRC Resident Inspector

INPO Records Center

TEST !