## LICENSEE EVENT REPORT

	EIGENSEE EVENT REPORT
	CONTROL BLOCK: [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	MIDCCCISCODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T	SOURCE L 6 0 5 0 0 0 3 1 5 7 0 4 0 5 8 3 8 0 4 1 9 8 3 9
(2)21	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	L DURING NORMAL OPERATIONS, WHILE PERFORMING A NON-ROUTINE TEST, THE CABLE VAULT HALON
0 3	SYSTEM FAILED TO MEET THE DESIGN CONCENTRATIONS, AND WAS DECLARED INOPERABLE. THIS IS
0 4	CONTRARY TO T.S. 3.7.9.4. THE PROVISIONS OF ACTION ITEM "A" OF T.S. 3.7.9.4 WERE
0 5	LINSTITUTED AT THIS TIME AND WILL CONTINUE IN EFFECT UNTIL THE SYSTEM IS RETURNED TO
0 6	LOPERABLE STATUS. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.
0 7	
0 8	
7 8	SYSTEM CAUSE CAUSE SUBCODE SUB
	TO REPORT NUMBER 21 22 23 23 SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE TYPE TYPE
	ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	THE CAUSE FOR THIS SYSTEM TO FAIL TO ACHIEVE DESIGN CONCENTRATION HAS NOT BEEN
11	DETERMINED AT THIS TIME. REVIEW OF TEST DATA AND FURTHER SYSTEM REVIEW AND TESTING
1 2	WILL CONTINUE. FURTHER REPORTS WILL BE FORWARDED UNDER THE REQUIREMENTS ESTABLISHED
1 3	BY TECHNICAL SPECIFICATIONS.
1 4	
	ACILITY TATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY
1 5	E 28 1 0 0 0 29 N/A C 3 NON-ROUTINE TEST
	TIVITY CONTENT 12 13 44 45 46 LEASED OF RELEASE AMOUNT OF ACTIVITY 35 N/A LOCATION OF RELEASE 36
8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7	0 0 0 37 Z 38 N7A
12	NUMBER DESCRIPTION (41) N/A
8 5	OSS OF OR DAMAGE TO FACILITY 43  PDR ADOCK 05000315
8 9	2 (42) N/A S PDR
15 10 15 18	SHED DESCRIPTION 45  N/A  N/A
	NAME OF PREPARER Paul Jacques PHONE 616-465-5901