

Appendix

NOTICE OF VIOLATION

Howmet Turbine Components

License No. 13-18517-01

As a result of the inspection conducted on March 30, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified:

1. License Condition No. 12 requires that licensed material be used by, or under the supervision of a named individual.

Contrary to this requirement, the individual named on your license authorized to use byproduct material left your facility approximately three years ago and no amendment was made to authorize current users.

This is a Severity Level IV violation (Supplement VI).

2. License Condition No. 16 requires that licensed material be possessed and used in accordance with statements, representations, and procedures contained in application dated March 31, 1978 and letters dated April 14, 1978, and June 22, 1979.

Item No. 11 of the referenced application requires your survey meters to be calibrated annually.

Contrary to this requirement, as of the date of this inspection, March 30, 1983, your Victoreen survey meter Model No. 471 was last calibrated on July 28, 1981. This frequency does not meet the annual requirement.

This is a Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

4-26-83  
Dated

*S.R. Lasuk*  
for D. J. Sreniawski, Chief  
Materials Radiation Protection  
Section 2

8305030150 830427  
NMS LIC30  
13-18517-01 PDR