

UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76611-8064

JUN | 5 1994

Docket: 030-08719 License: 35-15194-01

Globe X-Ray Services, Inc. ATTN: Beverly S. Ozmun, President 8441 South Union Street Tulsa, Oklahoma 74132

SUBJECT: NRC INSPECTION REPORT 030-08719/94-01

This refers to the routine, unannounced inspection conducted by Ms. M. Linda McLean of this office on May 5-6, and 25, 1994. The inspection included a review of activities authorized by Byproduct Materials License 35-15194-01. At the conclusion of the inspection, the findings were discussed with members of your staff.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observation of activities in progress.

No violations or deviations were identified; therefore, no response to this letter is required.

The inspector noted that you have been proactive in implementing revised 10 CFR Part 20 regulations which were in effect January 1, 1994. Activities specifically noted were the extensive area surveys you conducted at your permanent radiographic installations and storage locations to assure compliance with the new dose limits to members of the general public; the comprehensive revised Part 20 training held in January 1994; and the written ALARA policy included in your operating and emergency manual.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the NRC Public Document Room.

9406220012 940615 03008719 ADOCK

210018

Globe X-Ray Services, Inc.

Should you have any questions concerning this letter, please contact the inspector identified above at (817) 860-8100.

Sincerely,

Charles X. ain

Charles L. Cain, Acting Chief Nuclear Materials Inspection Branch

CC:

14

4

Oklahoma Radiation Control Program Director

Globe X-Ray Services, Inc.

.

1

bcc: DMB - Original (IE-07) LJCallan SJCollins RAScarano DWeiss, OC/LFDCB (T-9E10) *WLFisher *CLCain *FAWenslawski *MLMcLean *NMIB *MIS System *RIV Files (2)

*W/IFS Form

| RIV: NMIB WIM | AC:NMIB(1AC | |
|---------------|-------------|--|
| MLMcLean | CLCain | |
| 06/14/94 | 06/14/94 | |

-3-

Globe X-Ray Services, Inc.

4

bcc: DMB - Original (IE-07) LJCallan SJCollins RAScarano DWeiss, OC/LFDCB (T-9E10) *WLFisher *CLCain *FAWenslawski *MLMcLean *NMIB *MIS System *RIV Files (2)

*W/IFS Form

| RIV:NMIB WIM | AC:NMIB(AC | |
|--------------|------------|--|
| MLMcLean | CLCain | |
| 06/14/94 | 06//4/94 | |