LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 1 1 Z I S 1 2 0 0 4 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 5 6 6 17 CAT 58 6
CON'T REPORT LIG 0 5 0 0 0 2 9 5 7 1 0 2 5 8 2 8 1 1 2 4 8 2 9
0 2 OA Fire pump was taken out-of-service on 10/18/82. Seven days later
[0]3 [it was still inoperable. Per TS 3.21.2.B a special report is required]
old outlining plans and procedures to be used to provide for loss of re-
0 5 [dundancy to the Fire Protection System. Parts are on order. The pump]
o 6 will be returned to service by the end of the year.
0 7
7 8 9 SYSTEM CAUSE CAUSE CODE CODE SUBCODE CODE SUBCODE COMP. VALVE SUBCODE SUBCODE SUBCODE
AB 10 E 12 B 13 P U M P X X 14 X 15 Z 16 SEQUENTIAL OCCURRENCE REPORT REVISION
17 REPORT 8 2
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
Redundancy is provided via the service water booster pumps, the diesel
driven fire pump and the service water pumps. The diesel driven fire
pump is being tested once per week. The system design and procedures
are adequate to provide for the loss of redundancy of OA fire pump.
No further report is necessary.
FACILITY STATUS TO THER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA C 31 Operator Observation
ACTIVITY CONTENT 12 13 RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA N
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION 41 PDR ADDCK 05000295
1 8 0 0 0 40 NA S PDR 1 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43)
1 9 Z 42 NA
PUBLICITY ISSUED DESCRIPTION 45 NA NA NA NA
7 8 9 10 68 69 80-5