	LICENSEE EVENT REPORT
	CONTROL BLOCK:
0 1 8	C   A   S   O   S   2   2   O   O   -   O   O   O   O   O   O   O
0 1 8	REPORT LL 6 0 5 0 0 0 3 6 1 7 1 0 1 8 8 2 8 1 1 1 1 8 8 12 9
0 2	Operating modes were changed from Mode 4 to Mode 3 with one train of
0 3	component cooling water improperly aligned such that Emergency Chiller E-335
0 4	was rendered inoperable. The completely redundant Unit 2 loop A Chiller E-336
0 5	remained operable throughout the event and public health and safety were not
0 6	compromised.
0 7	
0 8	<u></u>
0 9 7 8	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO.  17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE TAKEN ACTION ON PLANT METHOD HOURS (27) ATTACHMENT FORM SUB. SUPPLIER SUPPLIER MANUFACTURER SUPPLIER MANUFACTURER Z 9 9 9 9 26
10	Incomplete documentation of abnormal system alignments resulted in CCW
	supply to emergency chiller not being returned to normal prior to changing modes.
1 2	Operations personnel have been reinstructed and applicable procedures are being
13	reviewed and revised as necessary.
14	<u></u>
1 5	STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32    B   28   0   0   0   29   NA
	CTIVITY CONTENT  LEASED OF RELEASE  AMOUNT OF ACTIVITY 35  NA  LOCATION OF RELEASE 36
17	PERSONNEL EXPOSURES NUMBER 0 0 0 0 37 2 38 DESCRIPTION 39 NA  8212070259 821118
1 8	NUMBER O O O O O O O O O O O O O O O O O O O
1 9	TYPE DESCRIPTION NA NA
2 0	SSUED DESCRIPTION (45)  NA  NA  NA  NA  NA  NA  NA  NA  NA  N
	H. B. Ray HB Ray / New Marky 68 69 80 2