

ENCLOSURE 1

NOTICE OF VIOLATION

Carolina Power and Light Company
Brunswick Units 1 and 2

Docket Nos.: 50-325 and 50-324
License Nos.: DPR-71 and DPR-62

During an NRC inspection conducted on April 6 - May 6, 1994, violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violations are listed below:

- A. Technical Specification 6.8.1 (a) requires that written procedures shall be established, implemented, and maintained covering the activities recommended in Regulatory Guide 1.33, Appendix A, November 1972. Regulatory Guide 1.33, Appendix A, paragraph 8, recommends procedures for surveillance tests, inspections and calibrations.

Surveillance Procedure, 1-MST-RCIC 22M, Reactor Core Isolation Cooling (RCIC) Steam Line Low Pressure Instrument Channel Calibration, Revision 8C, Steps 7.5.22 and 7.5.32 requires two voltmeters be used to perform the calibration test.

Contrary to the above, on April 18, 1994, a licensee technician used a single voltmeter to perform the calibration test and this resulted in a RCIC isolation.

This is a Severity Level IV Violation (Supplement 1).

- B. Technical Specification 3.7.5 requires that an inoperable snubber be replaced or restored to operable status and an engineering analysis be performed, or the system be declared inoperable within 72-hours.

Contrary to the above, the licensee discovered that RHR Snubber 2-E11-69SS574 had defective anchor bolts on March 18, 1994. The snubber was not repaired, and an engineering analysis was not performed. The snubber anchor bolts were replaced on May 6, 1994.

This is a Severity Level IV Violation (Supplement 1).

Pursuant to the provisions of 10 CFR 2.201, Carolina Power and Light Company is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region II, and a copy to the Resident Inspector Brunswick Steam Electric Plant within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order or Demand for Information may be

Notice of Violation

2

issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Atlanta, Georgia
this 2nd day of June 1994