

November 4, 1982

DJS Ltr. #82-1120

James G. Keppler, Regional Administrator Directorate of Regulatory Operations - Region III U.S. Muclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Updated Reportable Occurrence Report #82-08/03X-1, Docket #050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2 (a), reactor protection system or engineered safety feature instrument settings which are found to be less conservative than those established by the technical specifications but which do not prevent the fulfillment of the functional requirements of affected systems.

This revised report indicates the probable reason for the occurrence, includes the temperatures at which the five temperature switches tripped, and provides a correction to the list of previous occurrences.

D. J. Scott

Station Superintendent Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC