

Appendix

NOTICE OF VIOLATION

Mt. Sinai Medical Center

License No. 48-03280-01

As a result of the inspection conducted on November 10, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified:

1. License Condition No. 17 requires that licensed material be possessed and used in accordance with statements, representations, and procedures contained in application dated December 1, 1978 and referenced letters. This application states that your dose calibrators will be tested for linearity at least quarterly.

Contrary to the above, the Nuclear Medicine dose calibrator was not tested for linearity during second quarter 1981 nor first quarter 1982; and the Nuclear Cardiology dose calibrator was not tested during fourth quarter 1980 nor first quarter 1982.

This is a Severity Level V violation (Supplement VI).


2. 10 CFR 35.14(e)(1)(i) requires that your calibration or reference sealed sources be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, your gold-195 and two cesium-137 check sources and an americium-241 anatomical marker have been leak tested only annually.

This is a Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

11-23-82
Dated


D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1