

APPENDIX B

NOTICE OF DEVIATION

Entergy Operations, Inc.  
River Bend Station

Docket: 50-458  
License: NPF-47

During an NRC inspection conducted on April 24 through June 4, 1994, a deviation of your Updated Safety Analysis Report was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Action," 10 CFR Part 2, Appendix C, the deviation is listed below:

- A. Updated Safety Analysis Report, Revision 4, Section 9.1.2.3.3 states, "Administrative procedures require periodic sampling of the leak test system on the spent fuel pool liner. Little or no leakage is expected during normal operations."

Contrary to the above, from initial licensing on November 20, 1985, until May 20, 1994, there was no documentation or other evidence to show that periodic sampling of the leak test system on the spent fuel pool liner had been implemented (458/9412-02).

Please provide to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555, with a copy to the Regional Administrator, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, Texas 76011, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, in writing within 30 days of the date of this Notice, the reason(s) for the deviation, the corrective steps which have been taken and the results achieved, the corrective steps which will be taken to avoid further deviations, and the date when your corrective action will be completed. Where good cause is shown, consideration will be given to extending the response time.

Dated at Arlington, Texas,  
this        day of                1994

9407130090 940705  
PDR ADOCK 05000458  
Q PDR