

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDICC 2 000 - 000000 - 00 41111 5

CON'T REPORT SOURCE L 05000316 1111182 121082 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 DURING NORMAL PLT. OPERATIONS A SEC. OFFICER FOUND DOOR TO U-2 CD DIESEL ENG. FUEL OIL DAY TANK ROOM HELD OPEN BY DOOR CLOSURE ARM AND A PIECE OF CONDUIT LEFT IN DOORWAY WHICH WOULD HAVE PREVENTED DOOR FROM CLOSING IF CLOSURE ARM HAD BEEN RELEASED. NO PERSONNEL IN AREA. DOOR WAS DESIGNATED AS TECH. SPEC. RELATED FIRE DOOR. IT HAS BEEN DETERMINED SINCE THIS EVENT THAT THIS DOOR SHOULD NOT BE A TECH. SPEC. DOOR. HOWEVER, AT TIME OF OCCURRENCE, IT WAS A VIOLATION OF PROCEDURAL REQUIREMENTS FOR SAFETY RELATED FIRE DOORS. PUBLIC HEALTH & SAFETY NOT AFFECTED. PREV. OCCURRENCES - SEE ATT. SHEET.

09 SYSTEM CODE AB 11 CAUSE CODE A 12 CAUSE SUBCODE X 13 COMPONENT CODE XXXXX 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16 LER/RP REPORT NUMBER 17 82 EVENT YEAR 18 095 SEQUENTIAL REPORT NO. 19 03 OCCURRENCE CODE 20 L REPORT TYPE 21 SHUTDOWN METHOD Z 22 HOURS 000 23 ATTACHMENT SUBMITTED N 24 NPRO-4 FORM SUB. N 25 PRIME COMP. SUPPLIER Z 26 COMPONENT MANUFACTURER Z9999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 CONDUIT WAS IMMEDIATELY REMOVED AND DOOR SECURED. INDIVIDUALS RESPONSIBLE COULD NOT BE DETERMINED. ELECTRICAL CONTRACT PERSONNEL HAD BEEN WORKING IN AREA. ALL ELECTRICAL CONTRACT PERSONNEL WERE REMINDED OF REQUIREMENTS FOR FIRE PROTECTION DOORS. THE SPECIFIC DOOR WILL BE REDESIGNATED AS A NON-SAFETY RELATED FIRE DOOR.

15 FACILITY STATUS E 28 % POWER 1100 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION SECURITY OBSERVATION 32

16 RELEASED OF RELEASE Z 33 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 0000 37 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 0000 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY ISSUED DESCRIPTION N 44 8212170268 821210 PDR ADOCK 05000316 S PDR NRC USE ONLY NAME OF PREPARER B. A. SVENSSON PHONE: 616-465-5901

SUPPLEMENT TO LER 82-095/03L-0

Previous Occurrences:

RO 315/82-026  
RO 315/82-033  
RO 316/82-049  
RO 316/82-052  
RO 315/82-053, 316/82-053  
RO 315/82-062, 316/82-062  
RO 315/82-064