NRC FORM 366 (12-81)	U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT	APPROVED BY OMB 3150-0011 EXPIRES 4-30-82
CC VTROL BLOCK:	(PLEASE PRINT OR TYPE	E ALL REQUIRED INFORMATION)
0 1 P A S E S 1 2 0 1 7 8 LICENSEE CODE 14	0 - 0 0 0 0 0 0 - 0 0 3 4	LICENSE TYPE SO ST CAT SO
CON'T 0 1 REPORT L 6 0 5 0 7 8 60 61 DOCK	0 0 3 8 7 7 1 1 0 7 8 2 EXT NUMBER 62 62 EVENT DATE	2 8 1 2 0 7 8 2 9
0 2 During the Startup Test	ting Program, the pressure instr	rumentation indicated
0 3 Zone I of secondary con	ntainment was not maintained at	the required vacuum.
0 4 This is reportable per	6.9.1.9.b. No adverse conseque	ences existed in that
0 5 Zone I was at a negative	ve pressure as required, despite	instrument readings.
0 6		
0 7		
SYSTEM CAUSE	CAUSE	COMP. VALVE
SD X	2 Z 3 Z Z Z Z Z 2) Z 15 Z 16
TO HEFORT NUMBER 8 2	SEQUENTIAL OCCURRENCE	REPORT REVISION NO.
	ETHOD HOURS (22) SUBMITTED FORM	RD-4 PRIME COMP. COMPONENT 26 SUB SUPPLIER MANUFACTURER 26 N 24 Z 25 Z 9 9 9 9 47
CAUSE DESCRIPTION AND CORRECTION OF The instrumentation det	VEACTIONS ② termining the delta-P between th	ne atmosphere and Zone I
was functioning proper	ly. High wind conditions caused	the momentary deviation.
[1]2 Additionally, Zones I	and III had a common external se	nsor. The sensor of
1 3 Zone III was separated	and moved. No additional event	s have occurred since
1 4 that time.		90
TACILITY STATUS 1 5 B 28 0 0 2 29 n/a	1 1 101	observation (32)
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF A	conviry (35) Loc	CATION OF RELEASE (36)
7 8 9 10 11 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTIO		
7 8 9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION (41)	n/a	40
180000	n/a	
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 1 0 7 (42)	n/a	
PUBLICITY (S) 8212	n/a 210347 821207	NOTE THE COLUMN
ISSUED OESCRIPTION (45) PDR	ADOCK 05000387 PDR	NRC USE ONLY
NAME OF PREPARER	.G. Mitchell	HONE (717) 542-2181 X524