



June 20, 1975  
L-75-304

Mr. Norman C. Moseley, Director  
Office of Inspection and Enforcement, Region II  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N. W., Suite 818  
Atlanta, Georgia 30303

Dear Mr. Moseley:

Re: IE:II:AKH  
50-250/75-7  
50-251/75-7

During the course of an inspection conducted by personnel from your office on May 12-14, 1975, an apparent deviation from an FSAR commitment was observed. The specific finding states:

"During an inspection of cable tray penetrations, two locations were observed which appeared to deviate from the fire stop installation commitment made in the FPL FSAR, page 8.2-9."

Response:

FSAR page 8.2-9 states in part:

"Cable trays passing through walls or floors are provided with fire stops as shown in Figure 8.2-19."

One tray of control cables in the Unit 4 control rod drive room (not Unit 3 as stated in the inspection report) and four large cable trays entering the auxiliary building above the main corridor doors did not have fire stops. All of these cable trays now have fire stops.

There is no proprietary information in the subject report.

Yours very truly,

*James R. Tomonto*

Robert E. Uhrig *for*  
Vice President

REU:MAS:nch

cc: Jack R. Newman, Esquire

8212290094 821130

PDR FOIA

SHCLISS82-534 PDR

A15

Florida Power and Light Company

Turkey Point 3 50-250/75-7

Turkey Point 4 50-251/75-7

Ltr to Florida Power and Light Company fm N. C. Moseley dtd: MAY 29 1975

IE Inspection Report Nos. 50-250/75-7 and 50-251/75-7

DISTRIBUTION

H. D. Thornburg, IE

IE:HQ (5)

Office of Standards Development

Division of Reactor Licensing (13)

Central Files

PDR

Local PDR

NSIC

TIC

State - Florida