

Appendix

NOTICE OF VIOLATION

Iowa Electric Light and Power
Company

Docket No. 50-331

As a result of the inspection conducted on October 1 through November 30, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

Technical Specification 6.8.1 requires, in part, that procedures be adhered to for the surveillance and testing area. Surveillance Test Procedure 41A006, Step 4.6.e requires that Valves V-18-07, V-18-08, and V-18-16 be locked in their required position.

Contrary to the above, the chain lock was not attached to the pipe following the performance of STP 41A006 on October 20, 1982, after Valves V-18-07, V-18-08, and V-18-16 were properly positioned.

This is a Severity Level V violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

J. F. Streeter, Chief
Projects Branch 2

8302080309 830126
PDR ADOCK 05000331
PDR
Q