

LICENSEE EVENT REPORT

Attachment to AEEM-83/0097

Page 1 of 1

CONTROL BLOCK:

							(1)
--	--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

0 1 M S G G S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T

0 1 7 8

REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 0 1 1 3 8 3 8 0 2 1 1 8 3 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On January 13, 1983, two fire rated doors in the Control Building (OCT10 and OC714,
0 3 | 189 feet elevation, west stairwell) were blocked open to support planned maintenance.
0 4 | On January 28, fire door OC709 (189 feet elevation Control Building) was blocked
0 5 | open to support planned maintenance. Hourly fire watches were established in
0 6 | accordance with T.S.3.7.7. The event had no effect on the health and safety of
0 7 | the public and did not constitute a threat to plant safety. The event is reported
0 8 | pursuant to T.S.6.9.1.13.b.

09		SYSTEM CODE A B		CAUSE CODE X		CAUSE SUBCODE Z		COMPONENT CODE Z Z Z Z Z Z				COMP. SUBCODE Z		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER/RO REPORT NUMBER 17		EVENT YEAR 8 3		SEQUENTIAL REPORT NO. —		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0					
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38
ACTION TAKEN X		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER Z	
39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54
ACTION TAKEN X		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER Z	
55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70
ACTION TAKEN X		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER Z	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The doors were blocked open to route hoses being used in planned maintenance

1 1 activities. Doors OCT10 and OC714 were restored on January 13. Door OC709 was

1 2 closed on January 29. This is a final report.

1 3

1 4

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	G	0	0	0	NA	A	Planned Activity	
7	8	9	10	11	12	13	14	15	16
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	Z	NA					
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	Z				
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0					
7	8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z							
7	8	9	10	11	12	13	14	15	16
PUBLICITY ISSUED		DESCRIPTION							
2	0	N							
7	8	9	10	11	12	13	14	15	16

NAME OF PREPARER Original signed by Ron Byrd

PHONE