-	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	C T M N S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 57 CAT 58
CON'T 0 1 8	REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During routine power operation, 2-SI-616 was taken out of service to perform
0 3	maintenance on the valve. The unit operated under Technical Specification action
04	statement 3.5.2.a for four hours and fifteen minutes. Similar LER's: None
0 5	
06	
07	
0 8 7 8	9 80
0 9	SYSTEM CAUSE CODE SUBCODE SUBC
	LER RO REPORT VEAR REPORT NO. OCCURRENCE REPORT TYPE NO. NO. OLIVIOR FUTURE ACTION FUTURE ACTION ON PLANT METHOD HOURS (22) ATTACHMENT FORM SUB SUPPLIER MANUFACTURER X 8 B 9 7 7 20 7 20 0 0 0 0 0 N 23 Y 24 A3 25 L 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
10	Inspection of the valve operation showed cracking in the operator casing. The cause
111	is currently under investigation by Limitorque and will be repaired when parts are
1 2	available. The valve was placed in its throttled position and returned to service.
1 3	
1 4	9 80
1 5	FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 LE 28 1 0 0 29 NA LA 31 Operator Observation 80
	ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA NA NA NA NA NA NA NA
1 7	PERSONNEL EXPOSURES NUMBER O 0 0 0 37 Z 38 DESCRIPTION 39 PERSONNEL INJURIES NA 80
1 8	NUMBER DESCRIPTION (41) NA NA
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA 80
20	PUBLICITY ISSUED DESCRIPTION 45 PDR ADOCK 05000336 PDR 68 69 80.5
	NAME OF PREPARER Joseph M. Bergin PHONE (203) 447-1791 X4462

ENCORS.E.PESENZER, EDIELETERATER



P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 666-6911

May 20, 1983 MP-5062

Dr. Thomas E. Murley Regional Administrator, Region I U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Reference:

Facility Operating License No. DPR-65

Docket No. 50-336

Reportable Occurrence RO 50-336/83-17/3L-0

Dear Dr. Murley:

This letter forwards the Licensee Event Report 83-17/3L-0 required to be submitted within thirty days pursuant to Millstone Unit 2 Appendix A Technical Specifications, Section 6.9.1.9.b, conditions leading to operation in a degraded mode permitted by a limiting condition. An additional three copies of the report are enclosed. Due to an administrative error, this report is being submitted two days late.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

Station Superintendent Millstone Nuclear Power Station

J. Mroczka

EJM/JMB:mo

Attachment: LER RO 50-336/83-17/3L-0

cc: Director, Office of Inspection and Enforcement, Washington, D. C. (30) Director, Office of Management Information and Program Control, Washington, D. C. (3)

U. S. Nuclear Regulatory Commission, c/o Document Management Branch, Washington, D. C. 20555