

APPENDIX A
NOTICE OF VIOLATION

Carolina Power & Light
Harris Unit 1

Docket No. 50-400
License No. CPPR-158

As a result of the inspection conducted on January 20 - February 20, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

10 CFR 50, Appendix B, Criterion V as implemented by PSAR Section 1.8.5.5 and CP&L's Corporate QA Program Section 6.2.5 requires that activities affecting quality be accomplished in accordance with procedures.

Contrary to the above, on January 26, 1983, two service water piping spool pieces were found to be unsupported at the 30 foot intervals which are required by construction procedure WP-102, Appendix A. One of the spool pieces, partially filled with water, was found unsupported for a distance of 31½ feet, and the other piece was found unsupported for a distance of 74 feet. Site records indicate that CP&L inspection personnel have identified at least five similar procedural violations in the last year involving failure to adequately support piping spool pieces.

This is a Severity Level V Violation (Supplement II.E.).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: APR 1 1983

APPENDIX A

NOTICE OF VIOLATION

Carolina Power & Light
Harris Unit 1

Docket No. 50-400
License No. CPPR-158

As a result of the inspection conducted on January 20 - February 20, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

10 CFR 50, Appendix B, Criterion V as implemented by PSAR Section 1.8.5.5 and CP&L's Corporate QA Program Section 6.2.5 requires that activities affecting quality be accomplished in accordance with procedures.

Contrary to the above, on January 26, 1983, two service water piping spool pieces were found to be unsupported at the 30 foot intervals which are required by construction procedure WP-102, Appendix A. One of the spool pieces, partially filled with water, was found unsupported for a distance of 31½ feet, and the other piece was found unsupported for a distance of 74 feet. Site records indicate that CP&L inspection personnel have identified at least five similar procedural violations in the last year involving failure to adequately support piping spool pieces.

This is a Severity Level V Violation (Supplement II.E.).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: APR 1 1983