

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6
---	---	---	---	---	---

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	1	2	0	0	-	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4		5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	---

7 8 9 14 15 25 26 30 57 CAT 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

0	1	L	6	0	5	0	0	0	3	1	7	7	0	2	1	2	8	3	8	0	3	1	0	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 60 61 68 69 74 75 80
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During Mode 1 operation at 0840, Refueling Water Tank (RWT) level de-

0 3 creased to below the limit of T.S. 3.5.4.a. While conducting a valve

0 4 lineup to recirculate the RWT with No. 11 Spent Fuel Pool (SFP) Cooling

0 5 Pump, a flowpath was established between the RWT and No. 11 SFP. RWT

0 6 level decreased approximately 2 feet before the lineup was corrected.

0 7 Similar events: none.

0	8
---	---

7 8 9

0	9	F	C	11	D	12	Z	13	Z	Z	Z	Z	Z	14	Z	15	Z	16	17	8	3	21	0	1	1	26	0	3	28	L	30	0	32	G	18	H	19	Z	20	Z	21	0	0	0	0	37	N	23	N	24	Z	25	Z	9	9	9	26
---	---	---	---	----	---	----	---	----	---	---	---	---	---	----	---	----	---	----	----	---	---	----	---	---	---	----	---	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	---	---	---	----	---	----	---	----	---	----	---	---	---	---	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 5 The cause of this event was failure of the Operating Instruction (OI)

1 1 to require shutting SFP-194 (No. 11 SFP pump suction from No. 11 SFP)

1 2 prior to establishing a flowpath to the RWT. This OI has since been

1 3 corrected. All Operators will be informed of the details of this

1 4 event.

1	5	E	28	1	0	0	29	N/A	A	31	Operator Observation	32
---	---	---	----	---	---	---	----	-----	---	----	----------------------	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
PERSONNEL INJURIES NUMBER DESCRIPTION
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
PUBLICATION ISSUED DESCRIPTION
2 0 N 44 N/A
8303210621 830310
PDR ADOCK 05000317
S PDR
NRC USE ONLY
NAME OF PREPARER R. L. Wenderlich PHONE 301-269-4776