

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCC 1 2 000-0000000-000 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30CONT
011 REPORT SOURCE L 3 0 5 0 0 0 3 1 5 7 0 7 0 7 8 3 3 0 8 0 5 8 3 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 DURING A SURVEILLANCE TEST, THE EAST COMPONENT COOLING WATER MISC. HEADER ISOLATION

013 VALVE, CMO-415, WOULD NOT CLOSE COMPLETELY FROM THE CONTROL ROOM. THE VALVE COULD BE

014 OPERATED MANUALLY. THE VALVE WAS INOPERABLE FOR 2 HOURS AND 58 MINUTES WHICH WAS

015 NON-CONSERVATIVE WITH RESPECT TO T.S. 3.7.3.1. THE ACTION REQUIREMENTS WERE MET.

016 PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. SIMILAR PREVIOUS OCCURRENCES: DOCKET

017 050-316; 82-007, 82-010, 83-021, 83-027, 83-040.

018

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

SYSTEM CODE W B 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE B 15 VALVE SUBCODE D 16

EVENT YEAR 8 3 SEQUENTIAL REPORT NO. 0 6 4 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0

LEAD REPORT NUMBER 17 ACTION TAKEN Z 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER C 1 8 2 25

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

113 THE VALVE AND ITS MOTOR OPERATOR WERE INSPECTED. NO PROBLEMS WERE IDENTIFIED. A

114 RETEST OF THE VALVE WAS PERFORMED AND IT OPERATED SATISFACTORILY. SINCE THE CONDI-

115 TION COULD NOT BE DUPLICATED, NO FURTHER ACTION WAS WARRANTED.

116

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

FACILITY STATUS E 28 % POWER 0 8 6 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION SURVEILLANCE TEST 32

ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

117 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

118 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

119 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

120 PUBLICITY N 44 DESCRIPTION NA 45

21 N 46

NAME OF PREPAPER DAVID G. WIZNER

PHONE: 616-465-5901

8308220343 830805
PDR ADOCK 05000315
S PDR

1022

NRC USE ONLY



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

August 5, 1983

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137


Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,
the following reports are submitted:

RO 83-064/03L-0

Sincerely,


W.G. Smith, Jr.
Plant Manager

/cbm

cc: J.E. Dolan
M.P. Alexich
R.F. Kroeger
B. Germano
E. Swanson/N. DuBry RO:III
R.C. Callen MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (30 copies)
Dir., MIPC (3 copies)

AUG 08 1983

IE22 111