

SAFETY INSPECTION

DMB (FE07) 1/1

1. LICENSEE City of Rawlins P.O. Box 953 Rawlins, Wy. 82301		2. REGIONAL OFFICE U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 3000 Arlington, Texas 76012	
3. DOCKET NUMBER(S) 030-17187	4. LICENSE NUMBER(S) 49-19233-01	5. DATE OF INSPECTION May 17, 1983	

Licensee:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission's (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

1. Within the scope of this inspection, no violations were observed.

2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.

3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements.
THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11.

A. _____ was not properly posted to indicate the presence of a _____, 10 CFR 20.203(b), (c), (d), (e) or 34.42.

B. Containers located in _____ were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2).

C. _____ of sealed sources were not performed at the proper frequencies. 10 CFR _____ License Condition Number _____.

D. Records of *Leak Tests and Physical Inventories* were not properly maintained. 10 CFR _____ or License Condition Number *13 & 15*.

E. Documents were not properly posted or otherwise made available. 10 CFR 19.11.

F. Reports or notifications of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.

H. *Material was not stored at permitted address nor was a true address correct (License condition 10)*

I. _____

J. _____

K. _____

8306140093 830517
NMS LIC30
49-19233-01 PDR

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

<i>Liam Hirsch</i> SIGNATURE - LICENSEE	5-17-83 DATE	<i>Yuh M. Shupenn</i> SIGNATURE - NRC INSPECTOR	5/17/83 DATE
--	-----------------	--	-----------------

INSPECTOR'S REPORT
 (Continuation)

Office of Inspection and Enforcement

03017187

0301 (A)

VIOLATION SEVERITY OR DEVIATION

1	2	3	4	5	6
				✓	

SITE RELATED

A	C
B	D

VIOLATION OR DEVIATION (Enter up to 2400 characters for each item; if the text exceeds this number, it will be necessary to paraphrase. Limit lines to 50 characters each.)

1
 2 License condition 10 requires, in part, that the licensee shall store licensed
 3 material at 5th and Buffalo Street facility, Rawlins, Wyoming
 4
 5 Contrary to this requirement the licensee stored the licensed material at
 6 the Street Department Garage at 400 Duley St, Rawlins, Wyoming
 7
 8 This is a severity level V violation (supplement VI E)
 9
 10
 11
 12
 13
 14
 15
 16
 17
 18
 19
 20
 21
 22
 23
 24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47
 48

INSPECTOR'S REPORT
 (Continuation)
 Office of Inspection and Enforcement

03017187

NO	SEQ
0301	6
	B
	C
	D

5777-00B 6

VIOLATION SEVERITY OR DEVIATION

1	2	3	4	5	6
				✓	

SITE RELATED

A	C
B	D

VIOLATION OR DEVIATION (Enter up to 2400 characters for each item. If the text exceeds this number, it will be necessary to paraphrase. Limit lines to 50 characters each.)

1
 2 License Condition 13 requires, in part, that records of leak tests shall
 3 be maintained.
 4
 5 Contrary to this requirement, the records of leak tests were not
 6 maintained from April 1982 to May 17, 1983
 7
 8 This is a severity level IV violation (Supplement IV)
 9
 10
 11
 12
 13
 14
 15
 16
 17
 18
 19
 20
 21
 22
 23
 24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46

INSPECTOR'S REPORT
(Continuation)
Office of Inspection and Enforcement

03017187

NO. SEQ. 0301
B
C
D

577700B

VIOLATION SEVERITY OR DEVIATION

1 2 3 4 5 6
✓

SITE RELATED
A C
B D

VIOLATION OR DEVIATION (Enter up to 2400 characters for each item. If the text exceeds this number, it will be necessary to paraphrase. Limit lines to 50 characters each.)

1
2 License condition 15 requires, in part, that records of physical
3 inventory shall be maintained for two years from the date of the
4 inventory.

5
6 Contrary to this requirement, physical inventory records were not
7 maintained from April 1982 to May 1983

8
9 This is a severity level II violation (Supplement VI)



Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038

Nuclear Department

June 8, 1983

Director of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
7920 Norfolk Avenue
Bethesda, Maryland 20014

Attention: Mr. Steven A. Varga, Chief
Operating Reactors Branch 1
Division of Licensing

Gentlemen:

SPECIAL REQUALIFICATION TRAINING
SALEM GENERATING STATION
DOCKET NOS. 50-272 AND 50-311

The purpose of this letter is to request your concurrence in a special requalification training program for Mr. John D. Driscoll, Senior Reactor Operator License (SOP-3692), Assistant General Manager - Salem Operations. In your letter of July 13, 1982, you approved the revised requalification schedule for Salem licensed personnel based on the need for an extended time frame following the strike in the spring of 1982. Mr. Driscoll participated in the requalification training shift from August 20, 1982 to October 15, 1982. The evaluation of the training indicated deficiencies in sections J (Admin.) and F (Normal & Emergency Procedures). Mr. Driscoll was initially scheduled to complete that remedial program as well as the 1982/83 requalification training in a seven week period beginning March 28, 1983.

In late February 1983 Salem Unit 1 experienced a failure of the reactor trip breakers such that the reactor had to be tripped manually. The ensuing investigation and development of a corrective action program precluded Mr. Driscoll's attendance with the scheduled shift. As Salem Unit 2 was also in a scheduled outage at this time and short term requirements were being completed on Unit 1 prior to its startup, the continued presence of the Assistant General Manager at the station was required. Additionally, assignment of a new General Manager - Salem Operations in mid-April called for the continued presence of the Assistant General Manager during the transition period. As a result, Mr. Driscoll was unavailable to attend the last shift cycle of the 82/83 licensed operator requalification training which began on May 16, 1983.

8306140036 830608
PDR ADDCK 05000272
PDR

The Energy People

M003
1/0