



**SUPPLEMENT TO DVR**

DVR NO.			
STA	UNIT.	YEAR	NO.
D - 12	- 2	- 83	- 101

<b>PART 1</b>	<b>TITLE OF EVENT</b>	<b>OCCURRED</b>	
	Containment Spray Interlocks Surv. Performed Late	<u>7/14/83</u>	<u>1100</u>
	<b>REASON FOR SUPPLEMENTAL REPORT</b>	<b>DATE</b>	<b>TIME</b>
	Update cause code, cause subcode, future action, cause description and		
	corrective actions.		
<b>PART 2</b>			
ACCEPTANCE BY STATION REVIEW	<u>J. Brunner</u>	<u>John M. Howell</u>	
DATE	<u>8/26/83</u>	<u>8/26/83</u>	
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u>Douglas West</u>	<u>8/26/83</u>	
	STATION SUPERINTENDENT	DATE	



**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

August 25, 1983

DJS Ltr #83-840

James G. Keppler, Regional Administrator  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Updated Reportable Occurrence Report #83-54/03X-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems. This updated report is submitted to change the cause code and further define the cause description.

D.J. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U.S. NRC, Document Management Branch  
File/NRC

SEP 01 1983

IE 22  
///