



Boston Edison

Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360

E. T. Boulette, PhD
Senior Vice President - Nuclear


November 16, 1994
BECo Ltr. #94-124

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

Docket No. 50-293
License No. DPR-35

PNPS Core Shroud Repair

As we have discussed in various telephone calls and in our management meeting on October 4, 1994; Boston Edison commits to implement a pre-emptive core shroud repair during RFO-10, which we will begin on or before April 1, 1995. The core shroud repair design and engineering effort is on-going. Our shroud repair plans and analysis will be submitted to the NRC for review and approval no later than Friday, January 16, 1995. A copy of the current core shroud repair schedule is attached for your information and use. If additional information is required, please contact Mr. David Heard at (508) 830-8800 or Mr. Robert Haladyna at (508) 830-7904.


E. T. Boulette, PhD

ETB/RAH/nas/Rap94/CoreShrd

Attachment

cc: Mr. R. Eaton, Project Manager
Division of Reactor Projects - I/II
Mail Stop: 14D1
U. S. Nuclear Regulatory Commission
1 White Flint North
11555 Rockville Pike
Rockville, MD 20852

U.S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406

Senior Resident Inspector
Pilgrim Nuclear Power Station

9411220082 941116
PDR ADDCK 05000293
P PDR

A001
111

CORE SHROUD REPAIR

Date: 15NOV94
16:54

(DRAFT)

Page:1

