

*Southern California Edison Company*

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92674-0128

R. W. KRIEGER  
VICE PRESIDENT  
NUCLEAR GENERATION

February 7, 1995

TELEPHONE  
714 368 6255


U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Docket Nos. 50-361 and 50-362  
30-Day Report  
Licensee Event Report No. 95-001  
San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to 10 CFR 50.73(d), this submittal provides the required 30-day written Licensee Event Report (LER) for an occurrence involving a physical altercation within the Protected Area of Units 2 and 3. Since this occurrence is applicable to Units 2 and 3, a single report for Unit 2 is being submitted in accordance with NUREG-1022. Neither the health nor the safety of plant personnel or the public was affected by this occurrence.

If you require any additional information, please so advise.


Sincerely,



Enclosure: LER No. 95-001

cc: L. J. Callan, Regional Administrator, NRC, Region IV  
A. B. Beach, Director, Division of Reactor Projects,  
Region IV  
K. E. Perkins, Jr., Director, Walnut Creek Field Office, NRC,  
Region IV  
J. Sloan (USNRC Senior Resident Inspector, Units 1, 2 and 3)  
M. B. Fields, NRC Project Manager, San Onofre Units 2 & 3  
Institute of Nuclear Power Operations (INPO)

11011



9502150374 950207  
PDR ADOCK 05000361  
S PDR

LICENSEE EVENT REPORT (LER)

Facility Name (1) | SAN ONOFRE NUCLEAR GENERATING STATION, UNIT 2 | Docket Number (2) | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 1 | 1 | of | 0 | 1 | Page (3)

PHYSICAL ALTERCATION WITHIN THE PROTECTED AREA

EVENT DATE (5)				LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
Month	Day	Year	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Names	Docket Number(s)	
0	1	16	95	0	0	0	0	0	SONGS UNIT 3	0   5   0   0   0   3   6   2	

OPERATING MODE (9) | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10CFR (Check one or more of the following) (11)

POWER LEVEL (10)	0	9	7	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(c)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
				<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.36(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
				<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input checked="" type="checkbox"/> Other (Specify in Abstract below and in text)
				<input type="checkbox"/> 20.405(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	10 CFR 73.71(d)
				<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
				<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

Name | R. W. Krieger, Station Manager | TELEPHONE NUMBER | 7 | 1 | 4 | 3 | 6 | 8 | - | 6 | 2 | 5 | 5 | AREA CODE

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

Yes (If yes, complete EXPECTED SUBMISSION DATE) |  NO | Expected Submission Date (15) | Month | Day | Year

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At approximately 23:45 on January 16, 1995, with both Units at about 97% power, two Firewatch contractors (non-utility, non-licensed) were involved in a physical altercation (exchange of blows) inside a multipurpose lunch room in the Protected Area. The altercation was not related in any way to plant operations or plant safety; rather, it apparently related to Firewatch union accounting/financial matters.

A security officer entered the multipurpose lunch room at the conclusion of the altercation and determined supervisory involvement was required. The Firewatch supervisor arrived independently and immediately escorted individual #1 out of the Protected Area. Individual #1 was transported to Good Samaritan Hospital and diagnosed with a fractured rib. Edison management directed Security to remove individual #2 from the Protected Area at 01:00 on January 17, 1995.

A security officer and Operations personnel walked down plant areas occupied by the two individuals, from the time of the incident until they were escorted out of the Protected Area, verifying no unauthorized actions had occurred. Security suspended unescorted Protected Area access for both individuals at approximately 01:25 on January 17, 1995. Edison plans to permanently deny plant access for these two individuals.

In accordance with the requirements of 10 CFR 73.71(b), Edison reported this occurrence by telephone (NRC Log Event Number 28247) at 03:00 on January 17, 1995. Edison is providing this 30-day follow-up report in accordance with 10 CFR 73.71(d).

No required Firewatch postings were missed and there was no safety significance to this occurrence. There have been no LERs submitted for similar occurrences in the past three years.