

Licensee Event Report
LER 83-092/03L-0
Page 2 of 2

CAUSE DESCRIPTION AND CORRECTIVE ACTION (continued)

The heat tracing thermostat setpoint has been adjusted to compensate for the thermostat location.