

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [P] [A] [S] [E] [S] [1] [2] [0] [0] [-] [0] [0] [0] [0] [0] [-] [0] [0] [3] [4] [1] [1] [1] [1] [4] [ ] [ ] [5]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT  
[0] [1] [L] [6] [0] [5] [0] [0] [0] [3] [8] [7] [7] [0] [3] [2] [5] [8] [3] [8] [0] [4] [2] [2] [8] [3] [9]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0] [2] During the performance of a surveillance test, the CREOASS train A tripped for un-  
[0] [3] known reasons. There were no adverse consequences as the B train was available for  
[0] [4] service.

[0] [5]  
[0] [6]  
[0] [7]  
[0] [8]

[0] [9] [A] [A] [11] [A] [12] [C] [13] [B] [L] [O] [W] [E] [R] [14] [Z] [15] [Z] [16]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
[A] [18] [Z] [19] [Z] [20] [Z] [21] [0] [0] [0] [0] [N] [23] [N] [24] [A] [25] [T] [2] [6] [5]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1] [0] The trips were caused by the fan belts coming off the fan pulley. This occurred be-  
[1] [1] cause of improperly installed/misaligned shaft bearings which allowed the shaft to  
[1] [2] "back out", misaligning the fan pulley and allowing the fan belts to become disen-  
[1] [3] gaged. The belts were replaced and bearings and fan pulley re-aligned on the "A"  
[1] [4] fan. The "B" fan will be inspected to prevent a similar event.

[1] [5] [B] [28] [0] [0] [0] [29] NA [30] [B] [31] Surveillance Test [32]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

[1] [6] [Z] [33] [Z] [34] NA [35] NA [36]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

[1] [7] [0] [0] [0] [37] [Z] [38] NA [39]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

[1] [8] [0] [0] [0] [40] NA [41]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
PERSONNEL INJURIES NUMBER DESCRIPTION

[1] [9] [Z] [42] NA [43] B305110247 830422 PDR ADOCK 05000387 S PDR  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

[2] [0] [N] [44] NA [45]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
PUBLICITY ISSUED DESCRIPTION