

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	W	A	I	W	I	N	I	P	I	2	0	0	0	1	0	0	0	0	1	0	0	3	4	1	0	0	0	4	1	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	

CON'T	REPORT SOURCE	L	8	0	1	5	1	0	1	0	1	3	9	7	7	1	1	2	2	2	8	3	8	0	1	1	2	1	0	8	4	9
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 A loss of fire detection instrumentation occurred on 606 ft. elevation
03 of Reactor Building. This is a violation of Tech. Spec. 3.3.7.9. The
04 consequence was loss of the supervisory alarm indication of a potential
05 fire.
06
07
08

09	SYSTEM CODE	A	B	11	CAUSE CODE	B	12	CAUSE SUBCODE	A	13	COMPONENT CODE	X	X	X	X	X	X	14	COMP. SUBCODE	E	15	VALVE SUBCODE	Z	16	LER/RO REPORT NUMBER	8	17	EVENT YEAR	8	18	SEQUENTIAL REPORT NO.	0	19	OCCURRENCE CODE	0	20	REPORT TYPE	I	21	REVISION NO.	1	22	ACTION TAKEN	B	23	FUTURE ACTION	Z	24	EFFECT ON PLANT	Z	25	SHUTDOWN METHOD	Z	26	HOURS	0	27	ATTACHMENT SUBMITTED	N	28	NRC-4 FORM SUB.	N	29	PRIME COMP. SUPPLIER	X	30	COMPONENT MANUFACTURER	X	31	X	32	X	33	X	34	X	35	X	36	X	37	X	38	X	39	X	40	X	41	X	42	X	43	X	44	X	45	X	46	X	47	X	48	X	49	X	50
----	-------------	---	---	----	------------	---	----	---------------	---	----	----------------	---	---	---	---	---	---	----	---------------	---	----	---------------	---	----	----------------------	---	----	------------	---	----	-----------------------	---	----	-----------------	---	----	-------------	---	----	--------------	---	----	--------------	---	----	---------------	---	----	-----------------	---	----	-----------------	---	----	-------	---	----	----------------------	---	----	-----------------	---	----	----------------------	---	----	------------------------	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----	---	----

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Condensation shorted out the detection system thus requiring power supply
11 replacement. The action statement of Tech. Spec. 3.3.7.9.a.2 was
12 instituted. Power supply was replaced and the source of the condensation
13 is being corrected.
14

15	FACILITY STATUS	B	28	% POWER	0	29	OTHER STATUS	N/A	30	METHOD OF DISCOVERY	A	31	DISCOVERY DESCRIPTION	Supervisory Alarm Received	32	ACTIVITY CONTENT	Z	33	AMOUNT OF ACTIVITY	N/A	34	LOCATION OF RELEASE	N/A	35	PERSONNEL EXPOSURES	0	36	DESCRIPTION	N/A	37	PERSONNEL INJURIES	0	38	DESCRIPTION	N/A	39	LOSS OF OR DAMAGE TO FACILITY	Z	40	DESCRIPTION	N/A	41	PUBLICITY	Z	42	DESCRIPTION	N/A	43	ISSUED	Z	44	DESCRIPTION	N/A	45	NRC USE ONLY		46		47		48		49		50
----	-----------------	---	----	---------	---	----	--------------	-----	----	---------------------	---	----	-----------------------	----------------------------	----	------------------	---	----	--------------------	-----	----	---------------------	-----	----	---------------------	---	----	-------------	-----	----	--------------------	---	----	-------------	-----	----	-------------------------------	---	----	-------------	-----	----	-----------	---	----	-------------	-----	----	--------	---	----	-------------	-----	----	--------------	--	----	--	----	--	----	--	----	--	----

NAME OF PREPARER R. D. Catlow

PHONE: (509)377-2501 Ext. 4755