

LICENSEE EVENT REPORT

Attachment to AECM-83/0393

Page 1 of 1

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T REPORT SOURCE 80 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During an inspection, by the Fire Protection Coordinator, areas contain-
 ing safety related cable in the Aux. Bldg. were identified as not having
 smoke detectors. These areas were Room 1A605 on elevation 228 feet and
 Stairwell 1A12 on elevations 185 to 208 ft. An investigation revealed
 no combustibles in the area. An hourly fire watch was established in
 these areas. This condition has no affect on the health and safety of
 the public and does not constitute a threat to plant safety.

SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 12 13 COMPONENT CODE 13 14 COMP. SUBCODE 19 20 VALVE SUBCODE 20 21
 LER NO. REPORT NUMBER 17 21 22 EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 24 26 OCCURRENCE CODE 27 29 REPORT TYPE 30 31 REVISION NO. 32 32
 ACTION TAKEN 34 35 FUTURE ACTION 35 36 EFFECT ON PLANT 35 36 SHUTDOWN METHOD 36 37 HOURS 37 40 ATTACHMENT SUBMITTED 41 42 NPRO-4 FORM SUB. 42 43 PRIME COMP. SUPPLIER 43 44 COMPONENT MANUFACTURER 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

Smoke detectors in these areas were omitted from the orig. plant design.
 It has been determined that smoke detectors are not needed in Room
 1A605. DCR 82-573 provides for installation of smoke detectors in Stair-
 well 1A12. An hourly fire watch will be maintained in the interim.
 Smoke detector installation is expected to be completed by 9-1-83.

FACILITY STATUS 9 10 % POWER 10 12 OTHER STATUS 30 31 METHOD OF DISCOVERY 45 46 DISCOVERY DESCRIPTION 32 33
 ACTIVITY CONTENT 33 34 RELEASED OF RELEASE 33 34 AMOUNT OF ACTIVITY 35 36 LOCATION OF RELEASE 36 37
 PERSONNEL EXPOSURES NUMBER 11 12 TYPE 12 13 DESCRIPTION 39 40
 PERSONNEL INJURIES NUMBER 11 12 DESCRIPTION 41 42
 LOSS OF OR DAMAGE TO FACILITY TYPE 12 13 DESCRIPTION 43 44
 PUBLICITY ISSUED 44 45 DESCRIPTION 45 46
 8307250289 830712
 PDR ADOCK 05000416
 S PDR

NAME OF PREPARED M. V. Rohrer

PHONE

NRC USE ONLY

IF22



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

83 JUL 19 10:28 1983

JAMES P. MCGAUGHY, JR.
VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Update Report - Omission of
Smoke Detectors from
Original Plant Design
LER 82-060/01 X-2
AECM-83/0393

This letter submits an update to previous reports submitted on September 22, 1982, and March 30, 1983. The event for which the report was submitted occurred on September 10, 1982, when during a inspection by the Fire Protection Coordinator, two areas in the Auxiliary Building were found to have no smoke detectors.

It has been determined that smoke detectors are not needed in Room 1A605. A design change for installation of smoke detectors in Stairwell 1A12 was requested under DCR 82-573. Smoke detector installation is expected to be completed by September 1, 1983. Attached is LER 82-060/01 X-2.

Yours truly,

J.P. McGaughy
for J. P. McGaughy

JPM:sap
Attachment

cc (See Next Page)

OFFICIAL COPY

1622

MISSISSIPPI POWER & LIGHT COMPANY

AECM-83/0393

Page 2

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555