Dear Congressman Walker:

I am responding to your letter to Chairman Palladino dated December 16, 1983 in which you describe the concerns of your constituent, Ms. Francine Taylor, regarding the restart of Three Mile Island, Unit 1 (TMI-1). While Ms. Taylor has provided you with a number of documents addressing a diversity of issues, we assume that her specific concerns focus on the adequacy of the TMI-1 emergency feedwater flow indicators, and on the competence and integrity of GPU management. These are two of the many issues being addressed under the TMI-1 Restart proceedings.

By Order dated August 9, 1979, the Commission ordered that GPU Nuclear, among other things, provide emergency feedwater flow indication in the TMI-1 control room prior to any restart of TMI-1. The indication system subsequently proposed by GPU Nuclear was reviewed and found acceptable by the NRC staff. subject to satisfactory verification testing of the final installation. At the completion of the verification testing, GPU Nuclear advised the staff by letter dated November 23, 1983, that the indication system, as installed, did not meet the accuracy criteria of + 10% because of indicated oscillations at low flow conditions. However, GPU Nuclear concluded that the oscillations at low flows did not affect the functional capability of the emergency feedwater system or the ability of the operator to take proper action, and therefore concluded that the installed system remains acceptable. The staff is reviewing this matter and will provide its Safety Evaluation to the Commission and parties to the TMI-1 Restart proceeding when complete. Since emergency feedwter flow indication is one of the modifications that must be complete and so certified by the staff prior to any restart, this issue will be resolved prior to any restart of TMI-1.

The issue of GPU management competence and integrity will similarly have to be resolved to the Commission's satisfaction prior to any restart of TMI-1. The Commission is presently considering alternatives for addressing this issue.

Sincerely,

(Signed) T. A. Rehm

William J. Dircks Executive Director for Operations

* SEE PREVIOUS CONCURRENCE SHEET (REVISED IN EDO OFFICE)

1	r pl	1
0	1	1
	N	1

OFC	:ORB#4;DL*	:ORB#4:DL*	:AD:OR:DL*	:D:DL*	:NRR:D*	:OELD*	:EDO
	:JVanVliet;pv	:JStolz	:GLainas	:DEisenhut	:HDenton	:JGray	:WJDircks
DATE	:01/16/84	:1/16/84	:01/16/84	:01/16/84	:01/23/84	:01/17/84	:01/24/84

DISTRIBUTION FOR GREEN TICKET 13906

Docket File w/incoming NRC PDR w/incoming L PDR w/incoming ORB#4 Rdg EDO Rdg HDenton ECase OELD OCA-3 MBridgers EDO 13906 Program Support, NRR MJambor DNottingham DEisenhut JHel temes JVan Vliet w/incoming & ticket RIngram w/incoming & ticket JSto1z Green Ticket File w/incoming & ticket **TMurley** RDeYoung GCunningham **JFunches** TSpeis RMattson RVollmer THompson Grace BSnyder MGarver

Dear Congressman Walker:

I am responding to your letter to Chairman Palladino dated December 16, 1983 in which you describe the concerns of your constituent, Ms. Francine Taylor, regarding the restart of Three Mile Island, Unit 1 (TMI-1). While Ms. Taylor has provided you with a number of documents addressing a diversity of issues, we assume that her specific concerns focus on the adequacy of the TMI-1 emergency feedwater flow indicators, and on the competence and integrity of GPU management. These are two of the many issues being addressed under the TMI-1 Restart proceedings.

By Order dated August 9, 1979, the Commission ordered that GPU Nuclear, among other things, provide emergency feedwater flow indication in the TMI-1 control room prior to any restart of TMI-1. The indication system subsequently proposed by GPU Nuclear was reviewed and found acceptable by the NRC staff as documented in the TMI-1 Restart Safety Evaluation (NUREG-0680). By letter dated November 23, 1983, GPU Nuclear later advised the staff that the indication system, as installed, did not meet the accuracy conteria of ± 10% because of indicated oscillations at low flow conditions. However, GPU Nuclear concluded that the oscillations at low flows did not affect the functional capability of the emergency feedwater system for the ability of the operator to take proper action, and therefore concluded that the installed system remains acceptable. The staff is reviewing this matter and will provide its Safety Evaluation to the Commission and parties to the TMI-1 Restart proceeding when complete. Since emergency feedwater flow indication is one of the modifications that must be complete and so certified by the staff prior to any restart, this issue will be resolved prior to any restart of TMI-1.

The issue of GPU management competence and integrity will similarly have to be resolved to the Commission's satisfaction prior to any restart of TMI-1. The Commission is presently considering alternatives for addressing this issue.

AD-OR:DL

GLainas*

01/16/84

Sincerely,

William J. Dircks, Executive Director for Operations

*See previous white for concurrences.

JGrav*

1/17/84

EDO WDircks 1/ /84 D:DL(DEtsenhut 01/4/84 NRR/ HDenton 01/23/84

Dear Congressman Walker:

I am responding to your letter to Chairman Palladino dated December 16, 1983 in which you describe the concerns of your constituent, Ms. Francine Taylor, regarding the restart of Three Mile Island, Unit 1 (TMI-1). While Ms. Taylor has provided you with a number of documents addressing a diversity of issues, we assume that her specific concerns focus on the adequacy of the TMI-1 emergency feedwater flow indicators, and on the competence and integrity of GPU management. These are two of the many issues being addressed under the TMI-1 Restart proceedings.

By Order dated August 9, 1979, the Commission ordered that GPU Nuclear, among other things, provide emergency feedwater flow indication in the TMI-1 control room prior to any restart of TMI-1. The indication system subsequently proposed by GPU Nuclear was reviewed and found acceptable by the NRC staff as documented in the TMI-1 Restart Safety Evaluation (NUREG-0680). By letter dated November 23, 1983, GPU Nuclear later advised the staff that the indication system, as installed, did not meet the accuracy criteria of ± 10% because of indicated oscillations at low flow conditions. However, GPU Nuclear concluded that the oscillations at low flows did not affect the functional capability of the emergency feedwater system or the ability of the operator to take proper action, and therefore concluded that the installed system remains acceptable. The staff is reviewing this matter and will provide its Safety Evaluation to the Commission and parties to the TMI-1 Restart proceeding when complete. Since emergency feedwater flow indication is one of the modifications that must be complete and so certified by the staff prior to any restart, this issue will be resolved prior to any restart of TMI-1.

The issue of GPU management competence and integrity, as impacted by the recent criminal indictments, will similarly have to be resolved to the Commission's satisfaction prior to any restart of TMI-1. The Commission is presently considering the alternatives for addressing this issue.

Sincerely.

William J. Dircks, Executive Director for Operations

ORB#4:DL ORB#4:DL JWayViet;cf JStolz# 01/16/84 01/16/84 AD-OR:DL GLainas 01/16/84 01/19/8401/ /84

NRR HDenton

Dear Congressman Walker:

I am responding to your letter to Chairman Palladino dated December 16, 1983 in which you describe the concerns of your constituent, Ms. Francine Taylor, regarding the restart of Three Mile Island, Unit 1 (TMI-1). While Ms. Taylor has provided you with a number of documents addressing a diversity of issues, we assume that her specific concerns focus on the adequacy of the TMI-1 emergency feedwater flow indicators, and on the competence and integrity of GPU management. These are two of the many issues being addressed under the TMI-1 Restart proceedings.

By Order dated August 9, 1979, the Commission ordered that GPU Nuclear, among other things, provide emergency feedwater flow indication in the TMI-1 control room prior to any restart of TMI-1. The indication system subsequently proposed by GPU Nuclear was reviewed and found acceptable by the NRC staff as documented in the TMI-1 Restart Safety Evaluation (NUREG-0680). By letter dated November 23, 1983, GPU Nuclear later advised the staff that the indication system, as installed, did not meet the accuracy criteria of ± 10% because of indicated oscillations at low flow conditions. However, GPU Nuclear concluded that the oscillations at low flows did not affect the functional capability of the emergency feedwater system or the ability of the operator to take proper action, and therefore concluded that the installed system remains acceptable. The staff is reviewing this matter and will provide its Safety Evaluation to the Commission and parties to the TMI-1 Restart proceeding when complete. Since emergency feedwater flow indication is one of the modifications that must be complete and so certified by the staff prior to any restart, this issue will be resolved prior to any restart of TMI-1.

The issue of GPU management competence and integrity, as impacted by the recent criminal indictments, will similarly have to be resolved to the Commission's satisfaction prior to any restart of TMI-1. The Commission is presently considering the alternatives for addressing this issue.

Sincerely,

William J. Dircks, Executive Director for Operations

ORB#4:DL ORB#4:DL JVanvillet;cf JSto12 01/1/84 01/1/84

0ELD D:DL 02/ 984 01/

D:DL NRR DEisenhut HDenton 01/ /84 01/ /84

for distribution: See next page

Rop. Robert S.	. Walker		ACTION CONTROL	DATES /	790/84 13906
			NTERIM REPLY		12/18/83
Chairman Palladino			INAL REPLY	1,	PREPARE FOR SIGNATURE
			TLE LOCATION	14 100 40	OF: OCHAIRMAN DEXECUTIVE DIRECTOR
			1/25/88		EXECUTIVE DIRECTOR
installed in 1 criteria or th	irce Center iwater flow TMI I do not ne SPU's com	meet NRC's)	112- Va	nviet
emergency feed installed in 1	irce Center iwater flow TMI I do not ne SPU's com	concerning ments instruments meet NRC's	5	112- Va	nviet
emergency feed installed in 1 criteria or th restart process	irce Center water flow TMI I do not me ePU's com ading	concerning aer fastruments meet NRC's mittment in information south Murley Beyoung	NG S		nviet
emergency feed installed in 1 criteria or th restart process ASSIGNED TO Denton, MRR	irce Center iwater flow TRI 1 do not ie GPU's com iding DATE 12/21/83	concerning aer instruments meet NRC's mittment in INFORMATION HOUTE Murley	NG S	3-2655	nviet

NRC FORM 2°2 (6-10) PRINCIPAL CORRESPONDENCE CONTROL

No. SECY-83-2655	Logging Date 12/20/83
NRC :	SECRETARIAT
TO: Commissioner	Gen. Counsel Solicitor Secretary Inspector & Auditor Policy Evaluation
inctnuments installed 1	Date 12/16/83 Incern re new emer leedwater flo n TMI 1does not meet NRC's ttment in the restart proceedin
Prepare reply for signature of: Chairman Commissioner EDO, GC, CL, SOL, PA, SEC Signature block omitted Return original of incoming of	CY, IA, PE R-5 TMI 1Met Ed
XX For direct reply* Suspens For appropriate action For information	Rec'd Off. EDD 1-83 Date 12-1-83 Time
EA Coinion	billie
For the Commission: *Send three (3) copies of	f reply to Secy Correspondence and Records Brand ACTION SLI

(3-82)