POWER & LIGHT P. D. BOX 6008 . NEW ORLEANS. LOUISIANA 70174 . (504) 366-2345

August 16, 1983

W3183-0284 Q-3-A35.07.82

Mr. John T. Collins Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3

Docket No. 50-382

Significant Construction Deficiency No. 82

"Rent Control Element Assembly Rods"

Second Interim Report

REFERENCE: LP&L Letter W3I83-0186 dated May 25, 1983

Dear Mr. Collins:

The above referenced letter indicated that further information would be submitted to the USNRC by August 16, 1983.

At the present time, sixteen CEAs have been returned to Combustion Engineering for evaluation. Nine CEAs were determined to be out of specification. These CEAs were disassembled, the affected fingers were straightened and re-inspected, and the CEAs were re-assembled. The other seven were judged acceptable. Upon return of these CEAs, presently scheduled for September, Combustion Engineering will re-inspect all ninety-one as a final precaution against use of defective CEAs.

A final report will therefore be submitted to the USNRC by October 14, 1983.

Very truly yours,

F. J. Drummond, Manager

Engineering & Technical Services

FJD: WAC: MAL: SSTG

- cc: 1) Director
 Office of Inspection & Enforcement
 U. S. Nuclear Regulatory Commission
 Washington, D.C. 20555
 - 3) Mr. E. L. Blake

- Director
 Office of Management
 Information and Program Control
 U. S. Nuclear Regulatory Commission
 Washington, D. C. 20555
- 4) Mr. W. M. Stevenson

8308300588 830816 PDR ADOCK 05000382 S PDR

IE-27 1/0