

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

5, P.O. 917-926

NARRATIVE REPORT  
FOR LER 50-366/1983-067

LICENSEE : GEORGIA POWER COMPANY  
FACILITY NAME : EDWIN I. HATCH  
DOCKET NUMBER : 50-366

Tech. Specs. section(s) which requires report:

This 30-day LER is required by Tech. Specs. section 6.9.1.9.c due to the event's showing that the unit was not meeting the requirements of Tech. Specs. section 6.8.3.b.

Plant conditions at the time of the event(s):

This event was discovered on 08/11/83 with the reactor mode switch in the run position and reactor power at 2259 MWt (approximately 93% power).

Detailed description of the event(s):

On 08/03/83, while performing HNP-2-3820M "SAFETY RELIEF VALVE POSITION PRIMARY AND SECONDARY INDICATORS F. T. & C." procedure, a typographical error was discovered. Plant personnel corrected the procedure and the temporary change was approved by 2 members of the plant management staff. The procedure was performed on 08/03/83. On 08/11/83, it was determined that neither of the 2 members of the plant management that had approved the procedure correction on 08/03/83 held a Senior Reactor Operator's License.

Consequences of the event(s):

Plant operation was not affected by this event. The health and safety of the public were not affected by this event.

Status of redundant or backup subsystems and/or systems:

The redundant or backup subsystems and/or systems were not affected by this event.

Justification for continued operation:

Plant operation was not affected by this event.

If repetitive, number of previous LER:

This event is non-repetitive.

Impact to other systems and/or Unit:

This event had no impact on any other Unit 2 systems or on Unit 1.

Cause(s) of the event(s):

The cause of this event is personnel error.

Immediate Corrective Action:

When this event was discovered on 08/11/83, the procedure change was approved by a member of the plant management staff who holds a Senior Reactor Operator's License.

Supplemental Corrective Action:

The procedure correction (i.e., change) was documented, reviewed by the PRB, and approved by the General Manager within 14 days of implementation as required by Tech. Specs. section 6.8.3.c.


Scheduled (future) corrective action:

None required.

Action to prevent recurrence (if different from corrective actions):

The responsible personnel will be counseled on the circumstances leading to this event.

Georgia Power Company  
Post Office Box 439  
Baxley, Georgia 31513  
Telephone 912 367-7781  
912 537-9444



Edwin I. Hatch Nuclear Plant


September 9, 1983  
GM-83-463

PLANT E. I. HATCH  
Licensee Event Report  
Docket No. 50-366

United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

Attached is Licensee Event Report No. 50-366/1983-067. This report is required by Hatch Unit 2 Technical Specifications Section 6.9.1.9.c.

  
H. C. Nix  
General Manager

*stc*  
HCN/SBT/djs

xc: R. J. Kelly  
G. F. Head  
J. T. Beckham, Jr.  
P. D. Rice  
K. M. Gillespie  
S. B. Tipps  
R. D. Baker  
Control Room  
Document Control

OFFICIAL COPY

IE 22  
11