



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

83 SEP 15 9:36 AM '83
September 12, 1983

NUCLEAR PRODUCTION DEPARTMENT

U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Special Report 83-041/1 -
Update Report - Smoke
Detectors Covered During
Welding Activities
AECM-83/0559

This is an update to a previous report submitted June 7, 1983, for the following event. On April 24, 1983, smoke detectors in the upper and lower cable spreading rooms of the Control Building were covered and deactivated to prevent inadvertent actuation from welding activities. Action (b) of Technical Specification 3.3.7.9 was entered as part of the planned activity.

All smoke detectors associated with Special Report 83-041 were restored to operability by September 6, 1983. Since the smoke detectors were not restored within 14 days, this is submitted as a Special Report pursuant to Technical Specification 6.9.2. This condition had no effect on the health and safety of the public and did not constitute a threat to plant safety. This is a final report.

Yours truly,

L. F. Dale

for L. F. Dale
Manager of Nuclear Services

EBS/SHH:sap

cc: (See Next Page)

8309190472 830912
PDR ADOCK 05000416
S PDR

OFFICIAL COPY

TE 22

10

MISSISSIPPI POWER & LIGHT COMPANY

AECM-83/0559

Page 2

cc: Mr. J. B. Richard
Mr. R. B. McGehee
Mr. T. B. Conner
Mr. G. B. Taylor

Mr. Richard C. DeYoung, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555