

APPENDIX A
NOTICE OF VIOLATION

Florida Power and Light Company
St. Lucie 2

Docket No. 50-389
License No. NPF-16

As a result of the inspection conducted on September 11 - October 10, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification, Paragraph 6.8 requires that written procedures shall be established, implemented and maintained for those systems recommended in Appendix "A" of Regulatory Guide 1.33, Revision 2, February 1978. Two procedures require the 2B low pressure safety injection (LPSI) flow control valve (FCV-3301) to be "locked open", AP 2-0010123, Rev. 4, Administrative Control of Valves, Locks and Switches and OP 2-0410020, Rev. 5, HPSI/LPSI Normal Operation. Furthermore, Paragraph 8.1.5 of AP 2-0010123 requires that: "A motor operated valve under Administrative Control shall be tagged or locked at both the local handwheel and control switch."

Contrary to the above, procedures were not implemented in that during a routine walkdown of the LPSI system, the lock was found to be missing from FCV-3301. The LPSI system remained operable.

This is a Severity Level V Violation (Supplement II.D.2).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

NOV 14 1983

Date: _____

8402140283 840118
PDR ADOCK 05000035
Q PDR

APPENDIX A

NOTICE OF VIOLATION

Florida Power and Light Company
St. Lucie 2

Docket No. 50-389
License No. NPF-16

As a result of the inspection conducted on September 11 - October 10, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification, Paragraph 6.8 requires that written procedures shall be established, implemented and maintained for those systems recommended in Appendix "A" of Regulatory Guide 1.33, Revision 2, February 1978. Two procedures require the 2B low pressure safety injection (LPSI) flow control valve (FCV-3301) to be "locked open", AP 2-0010123, Rev. 4, Administrative Control of Valves, Locks and Switches and OP 2-0410020, Rev. 5, HPSI/LPSI Normal Operation. Furthermore, Paragraph 8.1.5 of AP 2-0010123 requires that: "A motor operated valve under Administrative Control shall be tagged or locked at both the local handwheel and control switch."

Contrary to the above, procedures were not implemented in that during a routine walkdown of the LPSI system, the lock was found to be missing from FCV-3301. The LPSI system remained operable.

This is a Severity Level V Violation (Supplement II.D.2).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: NOV 14 1983