

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [A] [L] [J] [M] [F] [1] [2] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [3] [4] [1] [1] [1] [1] [4] [ ] [ ] [ ] (5)

CONT

[0] [1] [L] [6] [0] [5] [0] [0] [0] [3] [4] [8] [7] [0] [8] [2] [5] [8] [3] [8] [0] [9] [1] [9] [8] [3] [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0] [2] At 2352 on 8/25/83, the A and B train chlorine detectors were declared inoperable  
[0] [3] due to broken detector tapes. Tech. Spec. 3.3.3.6 requires these detectors to be  
[0] [4] operable. Tech. Spec. 3.3.3.6 action statement requirements were met. Health/  
[0] [5] safety of the public was not affected. This LER is applicable to both Unit 1  
[0] [6] and Unit 2 at FNP.

[0] [7]  
[0] [8]

[0] [9] [S] [G] (11) [E] (12) [X] (13) [I] [N] [S] [I] [T] [R] [U] (14) [E] (15) [Z] (16)  
[17] [8] [3] [ ] [0] [5] [0] [ ] [0] [3] [L] [ ] [0]  
[A] (18) [Z] (19) [Z] (20) [Z] (21) [0] [0] [0] [0] [N] (23) [N] (24) [A] (25) [X] [9] [9] [9] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1] [0] An investigation revealed no cause for the tape failure. Following replacement  
[1] [1] of the tape cassettes, the A and B train chlorine detectors were declared  
[1] [2] operable at 0015 and 0005 on 8/26/83 respectively.  
[1] [3]  
[1] [4]

[1] [5] [E] (28) [1] [0] [0] (29) [NA] (30) [A] (31) Operator Observation (32)

[1] [6] [Z] (33) [Z] (34) [NA] (35) [NA] (36)

[1] [7] [0] [0] [0] (37) [Z] (38) [NA] (39)

[1] [8] [0] [0] [0] (40) [NA] (41)

[1] [9] [Z] (42) [NA] (43)

[2] [0] [N] (44) [NA] (45) NRC USE ONLY

NAME OF PREPARER

W. G. Hairston, III

PHONE:

(205) 899-5156