

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | J | M | F | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

0 1 | R | P | O | R | T | S | O | U | R | C | E | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 4 | 8 | 7 | 0 | 8 | 2 | 0 | 8 | 3 | 8 | 0 | 9 | 1 | 9 | 8 | 3 | 9

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1705 on 8/20/83 and again at 1815 on 8/29/83, the instrumentation channel

0 3 | associated with feedwater flow indicator FI-487 was declared inoperable when it

0 4 | drifted high. Tech. Spec. 3.3.1, in part, requires this channel to be operable.

0 5 | Tech. Spec. 3.3.1 action statement requirements were met. Health/safety of the

0 6 | public was not affected.

0 7 |

0 8 |

0 9 | I | A | 11 | E | 12 | G | 13 | I | N | S | T | R | U | 14 | X | 15 | Z | 16

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 | L | E | T | T | E | R | / | R | O | R | E | P | O | R | T | N | U | M | B | E | R | 8 | 3 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33

18 | A | 19 | Z | 20 | Z | 21 | Z | 22 | 0 | 0 | 0 | 0 | 23 | Y | 24 | Y | 25 | N | 26 | W | 1 | 2 | 0 | 27

21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33

EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | No cause could be determined for the first event. FNP-1-215.4 (Main Feedwater

1 1 | FT-487 Loop Calibration and Functional Test) was performed satisfactorily and

1 2 | the FI-487 instrumentation channel was declared operable at 0852 on 8/22/83.

1 3 | Following the second event, it was determined that the transmitter amplifier card

1 4 | was intermittently drifting. The card was replaced and following (See Attached)

1 5 | E | 28 | 1 | 0 | 0 | 29 | NA | 30 | A | 31 | Operator Observation | 32

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | 40 | NA | 41

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | 42 | NA | 43

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N | 44 | NA | 45

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

PUBLICITY ISSUED DESCRIPTION

NRC USE ONLY

W. G. Hairston, III

PHONE:

(205) 899-5156

Licensee Event Report
LER 83-055/03L-0
Page 2 of 2

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (Continued)

satisfactory performance of FNP-1-STP-215.4, the FI-487 instrumentation channel was declared operable at 1236 on 8/30/83.