

3150-0011  
EXPIRATION 4-30-62

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PHONE: (704) 373-7432

**DUKE POWER COMPANY**

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

September 16, 1983

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

USNRC REGION I  
ATLANTA, GEORGIA  
83 SEP 22 4 9:06  
TELEPHONE  
(704) 373-4531

Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street NW, Suite 2900  
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Unit 1  
Docket No. 50-369  
LER/RO-369/83-71

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/83-71. This report concerns T.S. 3.3.3.7, "As a Minimum, the Fire Detection Instrumentation for Each Fire Detection Zone Shown in Table 3.3-11 Shall be Operable". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

*H.B. Tucker / JB*

Hal B. Tucker

PBN:jfw  
Attachment

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. W. T. Orders  
NRC Resident Inspector  
McGuire Nuclear Station

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

OFFICIAL COPY

LC-2211