NRC F (12-81) 10 CFF	FORM 366 U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT	APPROVED BY OMB 3150-0011
10 CF F	CONTROL BLOCK: 1 1 PLEASE PRINT OR TYPE	ALL REQUIRED INFORMATION
01	1   C   A   S   O   S   2   2   O   O   -   O   O   O   O   O   O   O	LICENSE TYPE 30 4 57 CAT SS 5
CON'T	7	8 0 9 2 3 8 3 9
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  With Unit 2 in Mode 1 and the Core Operating Limit Supe	rvisory System (COLSS)
old out of service, calculations using Surveillance Test 5023-3-3.6 indicated that		
0 4	4]   the Departure from Nucleate Boiling Ratio (DNBR) margin	was not within allowable
0 5   limits. At 1900 the Action Statement associated with Limiting Condition		
o 6 for Operation (LCO) 3.2.4 was entered. This also occurred 9/1/83 at 0015,		
0 7 9/2/83 at 1218, 9/4/83 at 1536, and 9/8/83 at 0846 and 1011. Public		
ole health and safety were not affected.		
7	8 SYSTEM CAUSE CAUSE	SUBCODE SUBCODE
0 9	# 9 10 11 12 13 14	X (15) Z (16)  REPORT REVISION
	SEQUENTIAL SEQUENTIAL SECUENCE CODE	TYPE NO.
	NUMBER 21 22 23 24 26 27 28 29	30 31 32 COMPONENT (26
	TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM	N 24 N 25 Z 9 9 9 47
1 0	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ②  In each case, acceptable DNBR margin was verified with	in 15 minutes by restoring
1 1	1   the COLSS to service. Cause and corrective action to	prevent recurrence
1 2	2   are under review and will be reported in a revision to	this LER by November 15,
1 3	3   1983.	
114	4	
7	FACILITY OTHER STATUS (30) METHOD OF DISCOVERY DISC	r Observation (32)
7	8 9 10 12 13 44 45 46	ATION OF RELEASE (36)
1	6 Z 3 Z 3 NA NA NA	80
	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  7 0 0 0 37 Z 38 NA	
1	PERSONNEL INJURIES NUMBER DESCRIPTION (41)	
7	B 0 0 0 0 0 NA	40
I TI	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA	
7	PUBLICITY (5)	NRC USE ONLY
2	O NA	
1	Hame of the Area	714/492-7700 *°
B3100	070304 830923 ADBCK 05000361 PDR	TESS
3	I MIN	

RECEIVED

## Southern California Edison Company 1883 SEP 27

SAN ONOFRE NUCLEAR GENERATING STATION

SAN CLEMENTE, CALIFORNIA 92672

September 23, 1983

REGION VI

TELEPHONE (714) 492-7700

H. B. RAY STATION MANAGER

> U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region V 1450 Maria Lane, Suite 210 Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361 30-Day Report

Licensee Event Report No. 83-116

San Onofre Nuclear Generating Station, Unit 2

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-10 for San Onofre Unit 2, this submittal provides the required 30-day written report and a copy of the Licensee Event Report (LER) form for six occurrences involving Limiting Condition for Operation (LCO) 3.2.4 associated with the Departure from Nucleate Boiling Ratio (DNBR) margin. These events have been combined into a single report in accordance with NUREG-0161.

On August 23, 1983 at 1900, with Unit 2 in Mode 1 and as a result of the Core Operating Limit Supervisory System (CCLSS) being out of service, DNBR margin was determined in accordance with Procedure SO23-3-3.6. The DNBR margin determined in this manner was outside the region of acceptable operation as specified in Figure 3.2-1, "DNBR Margin Operating Limit Based on COLSS." As required by the Action Statement associated with Technical Specification 3.2.4, DNBR margin was determined to be within allowable limits within 15 minutes by returning COLSS to service and eliminating the need to rely on the more conservative DNBR margin calculated in accordance with SO23-3-3.6.

-2-September 23, 1983

Mr. J. B. Martin

There was no impact on the health and safety of plant personnel or the public because of this event.

DNBR margin was determined to be outside allowable limits during similar periods of COLSS inoperability on September 1, 1983 at 0015; September 2, 1983 at 1218; September 4, 1983 at 1536; September 8, 1983 at 0846; and September 8, 1983 at 1011. For each such occurrence, acceptable DNBR margin was verified within 15 minutes by restoring the COLSS to service.

Corrective action to improve the reliability of COLSS is currently under review. This review will be completed by November 15, 1983 at which time LER 83-116 will be revised to indicate cause and corrective action.

If there are any questions regarding these events, please contact me.

Enclosure: LER No. 83-116

cc: A. E. Chaffee (USNRC Resident Inspector, Units 2 and 3) J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission Division of Technical Information and Document Control

Institute of Nuclear Power Operations (INPO)